

To: Dorsey, Mike H[Mike.H.Dorsey@wv.gov]; Rusty[Rusty.T.Joins@wv.gov]
From: Linden, melissa
Sent: Wed 2/19/2014 10:07:20 PM
Subject: Photos of the current state of the boom
[SAM_2040.JPG](#)
[SAM_2041.JPG](#)
[SAM_2042.JPG](#)
[SAM_2043.JPG](#)
[SAM_2044.JPG](#)
[SAM_2045.JPG](#)
[SAM_2046.JPG](#)
[SAM_2047.JPG](#)
[SAM_2048.JPG](#)

Hi,

I mentioned to Richard Hackney who is the enforcement representative for WV DEP that the boom does not seem to be maintained well. I know that Scott specifically asked at the 10:30am meeting about the boom condition and he was told it looked good. I just went out to see the boom since it was deployed yesterday by Diversified and as you can see it is not well maintained. Richard Hackney did say that he would follow up with [REDACTED] from Diversified just wanted to let you know.

Thanks,

Melissa

From: [REDACTED] Ex. 6 - Personal Privacy [REDACTED]@TechLawInc.com]
Sent: Wednesday, February 19, 2014 4:33 PM
To: Linden, melissa
Subject: Photos of the boom deployed at Freedom Industries